

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/23/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/21/12 – 0700, 06/28/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Sheen observed at Ceresco Dam.</li> <li>• Ceresco Dam, observed temporary portage.</li> <li>• Ceresco Dam: Portage under construction.</li> <li>• Ceresco Dam: observed sweep boat.</li> <li>• Ceresco Dam: sheen observed at portage.</li> <li>• Observed boom removed from below Ceresco Dam.</li> <li>• Sheen observed at E4 boat launch.</li> <li>• Morrow Lake: observed public utilizing the lake.</li> <li>• Morrow Lake Delta: observed crew installing boom anchors.</li> <li>• Morrow Lake Delta: observed installed boom anchors.</li> <li>• E4 Boat Launch: observed crew loading boom to be deployed.</li> <li>• Morrow Lake Fan: sheen observed.</li> </ul>		
	Additional observations: None		
13:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			